
Supplemental Information



The switch assembly does not come with the 021-576 knob (2a). You may re-use your original, or order a new one.

Although every effort has been made to ensure the accuracy and clarity of this information, any suggestions that you may have that will improve the information (especially detailed installation notes) are welcome. Please use the simple email form on the "**Contact Us**" page on the Moss website: <u>http://www.mossmotors.com/AboutMoss/ContactUs.aspx</u>

If you prefer, you may call our Technical Services Department at 805-681-3411. So many people call us for help that we are often not able to answer the calls as fast as we'd like, and you may be asked to leave a message. We apologize in advance for the inconvenience. We will get back to you within 2 business days.



Moss Motors, Ltd. 440 Rutherford Street, Goleta, California 93117 In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400 Moss Europe Ltd. Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB In the UK: 020-8867-2020 FAX:- 020-8867-2030

Instruction Sheet 021-574_13H78 June 2010