

1 **Supplemental Information**
2 **for**
3 **021-671 or 11B5282 Handbrake Assembly**
4 **Austin Healey BN4 through BJ8**



20 ***About this Handbrake Assembly...***

21 We have listed these in our catalog for years, but up until recently there was no supplier willing to make
22 them. These are from a specialty manufacturer in England.

23
24 *The original bolts that secured the assembly remain a mystery.*

25 *The 100-6 used two 1B8895 screws with two 1B8896 spacers.*

26 *The BJ7-8 parts book shows the 1B8895 screw was superseded by another screw, 88G293.*

27 *If you have original samples of these pieces, we would like to borrow them so we can determine if we*
28 *have a suitable substitute in stock, and failing that, we will explore the possibility of having them made.*

29
30
31
32
33
34
35
36
37 *Although every effort has been made to ensure the accuracy and clarity of this information, errors and/or*
38 *omissions on our part are almost inevitable. Any suggestions that you may have that will improve the*
39 *information (especially detailed installation notes) are welcome. Please use the simple email form on the*
***"Contact Us"** page on the Moss website: <http://www.mossmotors.com/AboutMoss/ContactUs.aspx>*
If you prefer, you may call our Technical Services Department at 805-681-3411. So many people call us for
help that we are often not able to answer the calls as fast as we'd like, and you may be asked to leave a
message. We apologize in advance for the inconvenience. We will get back to you within 2 business days.



Moss Motors, Ltd.

440 Rutherford Street, Goleta, California 93117

In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400

Moss Europe Ltd.

Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB

In the UK: 020-8867-2020 FAX:- 020-8867-2030