


1 **Supplemental Information & Instructions**  
2 **for**  
3 **021-874 or AEC1230 Fuel Pipe, Carb-to-Carb**  
4 **BN4 CE48863 ON, BN6, BN7, BT7 (Twin SU)**



36 The 021-874 fuel pipe connects the front and rear carbs through the banjo bolts at the float bowls.  
37 The "single banjo" (1b) is for the rear carb.  
38 The 'double banjo' (1c) is for the front carb and it provides the connection (1e) for the 021-713 fuel hose  
39 (1d). The hose used in these photographs is a NOS original Petroflex hose. The replacement hoses look  
40 a little different, and must be ordered separately as they are not included with the fuel pipe.  
41  
42

43 *Any suggestions that you may have that will improve the information (especially detailed installation notes)*  
44 *are welcome. Please use the simple email form on the "Contact Us" page on the Moss website:*  
45 *<http://www.mossmotors.com/AboutMoss/ContactUs.aspx>*  
46 *If you prefer, you may call our Technical Services Department at 805-681-3411. So many people call us for*  
47 *help that we are often not able to answer the calls as fast as we'd like, and you may be asked to leave a*  
48 *message. We apologize in advance for the inconvenience. We will get back to you within 2 business days.*



**Moss Motors, Ltd.**

440 Rutherford Street, Goleta, California 93117  
In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400

**Moss Europe Ltd.**

Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB  
In the UK: 020-8867-2020 FAX:- 020-8867-2030