


1 Supplemental Information
2 for
3 **031-251 or AEC3072 HUB, THIRD-FOURTH**
4 **Austin Healey BJ8**

5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38



3RD/4TH GEAR SELECTOR HUB
BJ8

If used in a BJ8 the hub locking pin should be transferred
from the old
unit or new purchased.

These units are assembled ready for fitting and
should not be stripped.

This hub will not jump out of gear if fitted correctly
in accordance with the manual.

Race & Classic Sports Car Specialists

Denis Welch Motorsport
1004 Road, Yoxall, Burton on Trent, England. DE13 8NA Tel:+44(0)1543 444444 Fax: 01543 444444

The hub is (#25). By "locking pin" they are referring to the plunger 031-250 (#29), two required.

39
40
41
42
43

Although every effort has been made to ensure the accuracy and clarity of this information, errors and/or omissions on our part are almost inevitable. Any suggestions that you may have that will improve the information (especially detailed installation notes) are welcome. Please use the simple email form on the "Contact Us" page on the Moss website: <http://www.mossmotors.com/AboutMoss/ContactUs.aspx> If you prefer, you may call our Technical Services Department at 805-681-3411. So many people call us for help that we are often not able to answer the calls as fast as we'd like, and you may be asked to leave a message. We apologize in advance for the inconvenience. We will get back to you within 2 business days.



Moss Motors, Ltd.
440 Rutherford Street, Goleta, California 93117
In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400
Moss Europe Ltd.
Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB
In the UK: 020-8867-2020 FAX:- 020-8867-2030