


Regulator Interchange

Part # 141-900

The Lucas RF 95/2 (Moss Part Number 141-900) nine post regulator which incorporated a fuse box was replaced in 1951 by the Lucas RB 106/1 (142-000) regulator and SF6 fuse box (162-500). The nine post has since become a rarity. It is perfectly acceptable to replace a bad nine post regulator with the later regulator and fuse box. No permanent modification need be made; the wiring remains the same (except for a change of color in the horn wires) and nothing need be deleted or added. If a working nine post is found; it is an easy matter to revert to the older system. The newer parts may be kept as spares.



MOSS MOTORS, LTD.

P.O. Box 847 440 Rutherford Street Goleta, California 93117

(800) 235-6954 FAX (805) 692-2525

Instruction sheet #980-049 1/98