



## Supplemental Information & Instructions for 263-691 or BHA5292 Ignition Switch

Replacement for 1973 MGB, (c)294251 to 328100, GT from (c) 296001 to 328800  
As original for 1974 on MGB, (c)328101 on GT from (c) 328801 on



### About this Switch

*This switch (Fig 1) is correct for the 74 and later MGB. It has the correct plug for the harness used on those cars.*


*The switch for the 73 MGB is long gone, but the switch fitted from 74 on can be used if the white plug is removed. Strip the wires and solder on six of the 162-200 or 003632 bullet connectors. The wires on the US spec ignition switch are the same colors from 73-80. They do not have the same function. Consult your workshop manual for details.*



### Wiring Schematic for Current Switch



## Original Wiring Schematic for MGB 74 and on



Although every effort has been made to ensure the accuracy and clarity of this information, errors and/or omissions on our part are almost inevitable. Any suggestions that you may have that will improve the information (especially detailed installation notes) are welcome. Please use the simple email form on the **“Contact Us”** page on the Moss website: <http://www.mossmotors.com/AboutMoss/ContactUs.aspx>. If you prefer, you may call our Technical Services Department at 805-681-3411. So many people call us for help that we are often not able to answer the calls as fast as we'd like, and you may be asked to leave a message. We apologize in advance for the inconvenience. We will get back to you within 2 business days.



### Moss Motors, Ltd.

440 Rutherford Street, Goleta, California 93117  
In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400

### Moss Europe Ltd.

Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB  
In the UK: 020-8867-2020 FAX:- 020-8867-2030