


Supplemental Information

for

405-300 or AHH5154 Side Curtain Mounting Plate (3/8", 16 TPI)
405-100 or MB19331 Securing Nut, 'L' Handle (3/8", 16 TPI)
805-100 or 24B1656 Side Curtain Mounting Plate (5/16, 24 TPI)
805-110 or 24B540 Securing Wing-Nut (5/16, 24 TPI)



Ref	Moss US	Moss Europe	Description	Comments	Application
1a	405-300	AAA5154	Mounting plate	3/8" UNC or 16 TPI	AH BN4 to CE68959, MG TD, TF, MGA
1b	405-100	MB19331	Securing Nut, L handle		
1c	805-100	24B1656	Mounting plate	5/16" UNF or 24 TPI	AH BN4 from CE 68960 on thru BT7
1d	805-110	24B540	Securing Wing-Nut		

The triangular plates are identical, and it is very possible to find cars where the mounting plates are not technically correct. So long as the appropriate securing nuts are used, they are perfectly functional. If you plan on using new and old hardware together, be sure to identify what you have before you order the matching component.

Any suggestions that you may have that will improve the information (especially detailed installation notes) are welcome. Please use the simple email form on the "Contact Us" page on the Moss website:

<http://www.mossmotors.com/AboutMoss/ContactUs.aspx>

If you prefer, you may call our Technical Services Department at 805-681-3411. So many people call us for help that we are often not able to answer the calls as fast as we'd like, and you may be asked to leave a message. We apologize in advance for the inconvenience. We will get back to you within 2 business days.



Moss Motors, Ltd.

440 Rutherford Street, Goleta, California 93117
 In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400

Moss Europe Ltd.

Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB
 In the UK: 020-8867-2020 FAX:- 020-8867-2030

Instruction Sheet 405-100_MB19331_405-300_AAA5154_805-100_24B1656_805-110_24B540 June 2009