
## Supplemental Information & Instructions for

## 408-285 Stud, Windshield Side Support (upper) 408-295 Stud, Windshield Side Support (lower) MG TC, TD, TF



## About these studs....

The upper stud 408-285 (1a) is a little longer at 1 3/8" overall than the 408-295 (1b) lower stud, which is 1  $\frac{1}{4}$ " overall. The lower stud (1b) is distinguished by the flat on one side. They are made for us in small batches by a specialty hardware supplier in England. Given the limited demand for these, we are grateful that they are still available. The threads are 5/16 British Standard Brass, a Whitworth threadform.



## Moss Motors, Ltd.

440 Rutherford Street, Goleta, California 93117 In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400 **Moss Europe Ltd.** 

Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB In the UK: 020-8867-2020 FAX:- 020-8867-2030

Instruction Sheet 408-285\_408-295 February 2008