

Supplemental Information for 408-351 Smith's Sticker for Heater Face Plate Austin Healey BN1, BN2

The large round face plate of the Smiths heater assembly is very visible in the cockpit of the Healey 100. In the center of that plate there is a small recess. As the pictures below indicate, the recess in most cars has been empty because the small silver/black foil sticker fell off years ago.


The sticker was never listed in any parts book (although Smith's obviously had it made) and original examples are very rare.

The sticker has been reproduced and you can now finish that restoration...



"As well as the heater finished correctly in the crackle-black (but it has lost the Smiths badge, hence the blank area in the centre)..."

Clausager, **The Original Austin Healey**



"One stick-on foil "Smith's" label was fastened to a matching molded area in the center of the heater."

Moment, **Austin Healey Restoration Guide**

Although every effort has been made to ensure the accuracy and clarity of this information, any suggestions that you may have that will improve the information (especially detailed installation notes) are welcome.

Please use the simple email form on the "**Contact Us**" page on the Moss website:

<http://www.mossmotors.com/AboutMoss/ContactUs.aspx>

If you prefer, you may call our Technical Services Department at 805-681-3411. So many people call us for help that we are often not able to answer the calls as fast as we'd like, and you may be asked to leave a message. We apologize in advance for the inconvenience. We will get back to you within 2 business days.



Moss Motors, Ltd.

440 Rutherford Street, Goleta, California 93117

In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400

Moss Europe Ltd.

Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB

In the UK: 020-8867-2020 FAX:- 020-8867-2030