

454-231 & 262-340 Steering Wheel Center Hub

Installation Instructions For: MG TD & TF

440 Rutherford St. Goleta, CA 93117 1-800-667-7872 • FAX 805-692-2525 • www.MossMotors.com

Tools required:


- Phillips screw driver
- Flat file

Sometimes the center cap does not fit the steering wheel correctly. If you find a large gap on one side of the cap and a small gap or none at all on the opposite side, follow these simple instructions to even things out.

- 1. Remove the center cap from the steering wheel.
- 2. File some metal away from the area shown. It doesn't take much.



3. Test fit the center piece and install the screw. If the gap has evened out, you are done. Make sure the screw is tight. If the gap is still uneven repeat these steps until the cap evens out.





Although every effort has been made to ensure the accuracy and clarity of this information, any suggestions that you may have that will improve the information (especially detailed installation notes and photos) are welcome. These instructions were developed and written by Moss Technical Support. If you have any questions or difficulties with your installation of this product, telephone 800-667-7872 between 7:00 a.m. and 4:00 p.m., Pacific Time for assistance.

Moss Motors. Ltd.

440 Rutherford Street, Goleta, California 93117 In the US & Canada Toll Free (800) 667-7872 LOCAL (805) 681-3400 FAX (805) 692-2510



Moss Europe Ltd.

Hampton Farm Industrial Estate
Hampton Road West, Hanworth Middlesex, TW13 6DB
In the UK: 020-8867-2020 FAX:- 020-8867-2030