


1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24

## Supplemental Information for **583-000, 601960 or SP2501 Brake Caliper Kit** Austin Healey BJ8 FROM C26705 on Triumph from TR3 TS13046 thru TR6 to CC81078 (16P calipers)

### Contents of Kit

- 9 1a Bleed screw caps (2)  
10 1b Caliper Piston Seals (4)  
11 1c Dust Seals (4)



25  
26  
27

### Why is this Girling kit in a TRW box?

Lucas/Girling hydraulics were acquired by TRW. For several years, The TRW packaging included the name "Lucas", but that was discontinued in 2008. This caliper repair kit is the familiar SP2501.

28  
29  
30  
31  
32  
33  
34  
35

### What about Instructions?

The Lucas/Girling kits used to include a fairly generic instruction sheet, but the kits from TRW do not have any instructions at all. Please refer to your Factory Workshop Manual for the procedure for overhauling the calipers. If you do not have a workshop manual, DO NOT TRY AND REBUILD THE CALIPERS!

**Brakes are a Safety Critical System. Rebuilding the calipers requires some skill and if you have any doubts about your ability to perform the operations described in the Workshop Manual, have the work done by a professional.**

36  
37  
38  
39  
40  
41

*Any suggestions that you may have that will improve the information (especially detailed installation notes) are welcome. Please use the simple email form on the "Contact Us" page on the Moss website:*

<http://www.mossmotors.com/AboutMoss/ContactUs.aspx>

*If you prefer, you may call our Technical Services Department at 805-681-3411. So many people call us for help that we are often not able to answer the calls as fast as we'd like, and you may be asked to leave a message. We apologize in advance for the inconvenience. We will get back to you within 2 business days.*



#### Moss Motors, Ltd.

440 Rutherford Street, Goleta, California 93117

In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400

#### Moss Europe Ltd.

Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB

In the UK: 020-8867-2020 FAX:- 020-8867-2030

Instruction Sheet 583-000\_601960\_SP2501 June 2009