

Camshaft 1500

Part # 851-330

Engine block has no camshaft bearings. Camshaft journals are oversized to accomodate for minor wear in the block. Block MUST be line bored to allow camshaft bearings 0.0015 running clearance.

Camshaft 1500

Part # 851-330

Engine block has no camshaft bearings. Camshaft journals are oversized to accomodate for minor wear in the block. Block MUST be line bored to allow camshaft bearings 0.0015 running clearance.



MOSS MOTORS, LTD.

P.O. Box 847 440 Rutherford Street Goleta, California 93117
(800)235-6954 FAX (805)692-2525

Instruction sheet #980-228 8/02



MOSS MOTORS, LTD.

P.O. Box 847 440 Rutherford Street Goleta, California 93117
(800)235-6954 FAX (805)692-2525

Instruction sheet #980-228 8/02