



Alternator

PART# 851353

Core Identification Sheet

For your alternator to be an acceptable 851353

CORE must be complete, fully assembled. Core refund can take up to 30 days. The CORE must be tested to determine that internal non-replaceable electrical components have not been damaged or "burned up" beyond repair.

It must also have the features as called out in the photos below to comply as a "rebuildable." Returned Cores that do not meet these requirements are ineligible for core credit and will be rejected.

1. Single spade Positive and Negative mounting terminals.
2. Plastic red cover caveat must be present not cracked, smashed or damaged.
3. $\frac{7}{8}$ " approximate Stator Width (60 Amp Alternator).

