


1 **Supplemental Information**
2 **for**
3 **367-405 or CAM1388 Hose, Oil Separator to Breather, OE**
4 **367-400 Hose Kit, Oil Separator to Breather, Replacement**
5 **MGB, 1975 on**

6 **About this hose...**

7 *The original hose fitted to the MGB*
8 *(CAM1388) was formed with two different*
9 *sized ends. The hose ID was 1/2" at the*
10 *oil separator (on engine) and 5/16" ID at*
11 *the carb end. That hose is no longer*
12 *available, and given the limited demand, it*
13 *is unlikely that anyone will reproduce it.*

14
15 *Other replacement hoses consist of a*
16 *length of 1/2" hose, with one hose clamp;*
17 *the idea being to squeeze the 1/2" hose*
18 *down to 5/16" at the carburettor. This*
19 *solution was considered, and discarded as*
20 *less than ideal.*

21
22 *We have come up with a kit consisting of*
23 *two hoses and a black hose barb. No*
24 *hose clamps are included (or necessary)*
25 *because the hose is not pressurized.*
26



27 **Contents of Kit**

Ref	Moss US	Moss Europe	Description	Quantity
1a	052-256	NCA	HOSE, MOLDED, 1/2" HOSE	1 Each
1b	434-450	NCA	HOSE, FUEL, 5/16 IN, PER INCH	24 Inch
1c	052-462	NCA	ADAPTER,HOSE BARB, 5/16 TO 1/2	1 Each

28
29
30
31
32
33
34 *Although every effort has been made to ensure the accuracy and clarity of this information, any suggestions*
35 *that you may have that will improve the information (especially detailed installation notes) are welcome.*

36 *Please use the simple email form on the "Contact Us" page on the Moss website:*

<http://www.mossmotors.com/AboutMoss/ContactUs.aspx>

If you prefer, you may call our Technical Services Department at 805-681-3411. So many people call us for help that we are often not able to answer the calls as fast as we'd like, and you may be asked to leave a message. We apologize in advance for the inconvenience. We will get back to you within 2 business days.



Moss Motors, Ltd.

440 Rutherford Street, Goleta, California 93117
In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400

Moss Europe Ltd.

Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB
In the UK: 020-8867-2020 FAX:- 020-8867-2030