



# Starter

PART# 541-530

## Core Identification Sheet

For your starter to be an acceptable 541-530CORE it must be complete, fully assembled, with no broken mounting flanges.

**It must also have the features as called out in the photo below to comply as "rebuildable."**

Return Cores that do not meet these requirements are ineligible for core credit and will be rejected.

1. M418 on the case as illustrated in **Figure A**  
(A 2M100 case marking is also acceptable)
2. Starter drive (pinion/gear) as depicted in **Figure B** photo below.
3. Starters with the M418 or 2M100 designation on the case that have the **Figure C** style pinion/gear **will be accepted for a 50% reduced core credit.**


**Figure A**



**Figure B**



**Figure C**



---

**Rejected cores will be returned or discarded. Look for your confirmation email and open the attachment for details.**

---