**Supplemental Information** 682-338 Body Rubber Set

## 4 5

1

2

3

6 All items Listed below are included in this rubber kit. A circled number indicates

for

Austin Healey AH BN7, and BT7 Side Shift

7 that the item has been backordered and will follow as soon as possible.

8

Qty	Component	Description
1	021-337	SHIFT BOOT, SIDE SHIFT
2	021-412	PEDAL PAD
1	021-755	GROMMET, R/H BUMPER
1	021-756	GROMMET, L/H BUMPER
2	021-762	PAD, WINDSHIELD POST
1	021-763	WINDSHIELD SEAL
1	021-774	SEAL SET, OE SIDECURTAIN FRAME
1	021-775	SEALING RUBBER, TRUNK LID
9	031-359	BUFFER, RUBBER, FOR HOOD
4	159-600	FLASHER LAMP BODY, RUBBER
2	164-050	MOUNT RUBBER, HEADLAMP
1	280-165	GROMMET, FUEL FILLER
1	280-540	SEAL, LICENSE PLATE LAMP
2	282-350	PROP ROD STOP
1	680-928	SEAL SET, SCUTTLE
3	682-110	BUFFER, RUBBER, DOMED HEAD
1	682-180	STRIP, HOOD SEALING
2	682-200	GROMMET
1	698-018	GASKET SET, TRUNK HINGE, 4 PC
1	805-257	GASKET, TRUNK HANDLE

Although every effort has been made to ensure the accuracy and clarity of this information, errors and/or omissions on our part are almost inevitable. Any suggestions that you may have that will improve the information (especially detailed installation notes) are welcome. Please use the simple email form on the "Contact Us" page on the Moss website: http://www.mossmotors.com/AboutMoss/ContactUs.aspx If you prefer, you may call our Technical Services Department at 805-681-3411. So many people call us for help that we are often not able to answer the calls as fast as we'd like, and you may be asked to leave a message. We apologize in advance for the inconvenience. We will get back to you within 2 business days.



## Moss Motors, Ltd. 440 Rutherford Street, Goleta, California 93117 In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400 Moss Europe Ltd. Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB In the UK: 020-8867-2020 FAX:- 020-8867-2030 Instruction Sheet 682-338 October 1997, Revised December 2008