



# Alternator

PART# C31081/1

## Core Identification Sheet

For your alternator to be an acceptable C31081/1

**CORE must be complete, fully assembled, with no broken mounting flanges. Core refund can take up to 30 days. The CORE must be tested to determine that internal non-replaceable electrical components have not been damaged or "burned up" beyond repair.**

**It must also have the features as called out in the photos below to comply as a "rebuildable."** Return Cores that do not meet these requirements are ineligible for core credit and will be rejected.

1. Must have mounting terminal, for the single Spade Connector.
2. The plug and two Small Spade Connectors on the back must be there and not be broken. **If missing or broken no core credit.**
3. Must have have mounting, terminal for Large Spade Connector(s).
4. The Backing plate needs to have the LUCAS name cast.
5.  $\frac{5}{8}$ " approximate Stator Width (35 Amp Alternator). If they send the wide stator version, we will still give them 100% credit.

**Cores returned with broken mounting flanges will only receive 75% of the core credit.**

